



PLATE 5

DE MIER PHOTO

*Looking southwest at the community of Gibson Flats, March 18, 1969. The lake formed by melting snow had forced the evacuation of approximately one dozen families. This area remained inundated for more than six weeks. A need exists for urban flood protection measures as well as preventing future development in such hazardous areas.*